

## ECS/EMD Configuration Change Request

Page 1 of 2 Page(s)

1. Originator Joan H. Schessler	2. Log Date: 12/17/03	3. CCR #: 03-0834	4. Rev: —	5. Tel: 301.925.0426	6. Rm #: 3068C	7. Org. SEIT
8. CCR Title: Add RVARs for Synergy 2 and 3 Verification to the ECS VDB						
9. Originator Signature/Date Joan H. Schessler /s/ 12/16/03			10. Class II	11. Type: CCR	12. Need Date: 01/07/04	
13. CCR Sponsor Signature/Date Evelyn N. Nakamura /s/ 12/17/03			14. Category of Change: VDB		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): N/A			17. Schedule Impact: N/A		18. CI(s) Affected: N/A	
19. Release Affected by this Change: N/A		20. Date due to Customer: N/A		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Synergy 2 and Synergy 3 tickets were verified by analysis on the basis of Development I&T records, NCR records and operational status. At the ECS Transition Readiness Review, Raytheon's verification recommendations were furnished on an ECS Synergy 2,3 Verification Status Report. ESDIS has accepted these recommendations. A Requirement Verification by Analysis Report has been approved for each L3 requirement linked to Synergy 2 and 3 ticket(s) and will be the permanent record of ESDIS concurrence with this analysis. The ECS VDB needs to be updated to record the existence of the approved RVARs.						
24. Proposed Solution: (use additional sheets if necessary) Add the RVARs listed on sheet 2 of this CCR to the RVAR table in the ECS VDB with a status of Verified. Retain RVARs copies with this CCR.						
25. Alternate Solution: (use additional sheets if necessary)						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. SCDV CCB Chair (Sign/Date): Byron V. Peters /s/ 1/6/04			Disposition: <u>Approved</u> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. EDF CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

## ADDITIONAL SHEET

**CCR #:** 03-0834      **Rev:** — **Originator:** Joan H. Schessler

**Telephone:** 301.925.0426      **Office:** SEIT

**Title of Change:** Add RVARs for Synergy 2 and 3 Verification to the ECS VDB

Add the following RVARs to the ECS VDB RVAR table with status of Verified.

137A IMS-0785  
310 DADS2370  
311 DADS2676  
312 DADS0690  
313 DADS0760  
314 DADS2410  
315 DADS2430  
316 DADS2470  
317 DADS0810  
318 DADS2480  
319 DADS0660  
320 DADS2160  
321 IMS-0740

CM01AJA00 Revised 10/2/03

***ECS/EMD***